









<<BEFORE>>




<<AFTER>>










<<T71.1-1 West BEFORE>>




<<T71.1-1 West AFTER>>




T71.2-1 West BEFORE>>





T71.2-1 West AFTER>>




New Sandstone
Element which have been repositioned













<<C71.3.2 BEFORE>>




<<C71.3.2 AFTER>>





<<C71.3.1 BEFORE>>




<<C71.3.1 AFTER>>







<<T70.2 BEFORE>>




<<T70.1 BEFORE>>




<<T70.2 AFTER>>




<<T70.1 AFTER>>





New Sandstone
Element which have been repositioned



<<BEFORE>>





<<AFTER>>




 New Sandstone



 Element which have been repositioned









<<T65.4 BEFORE>>




<<T65.1 BEFORE>>




<<T65.4 AFTER>>





<<T65.1 AFTER>>





<<BEFORE>>




<<AFTER>>

New Sandstone


Element which have been repositioned


0 0.5 1 2 3 4 5M







Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon







 New Sandstone
 Element which have been repositioned





Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon







Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon



Restoration Project of Naga and Lion Statues and Balustrade
at Outer Gallery and East Causeway of Bayon




Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon




Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon

<<BEFORE>>



South Elevation [A]

<<AFTER>>




South Elevation [A]

Numbering without [*] follows after [58.2.8.]


New Sandstone
Element which have been repositioned



<<BEFORE>>




Top Plan




South Elevation

<<AFTER>>



Top Plan



South Elevation

■ New Sandstone
■ Element which have been repositioned



<<T57.3 BEFORE>>

Y60

X60


<<T57.3 AFTER>>

Y60

X60


<<T57.2 BEFORE>>

Y70



<<T57.2 AFTER>>

New Sandstone
Element which have been repositioned





No Plan

Y80

X60

X78 X-67 X-65 X-63 X-61 X-59 X-57





Restoration Project of Naga and Lion Statues and Balustrade at Outer Gallery and East Causeway of Bayon